



19B – SOFTWARE RELEASE NOTES

INFOTAINMENT MASTER CONTROLLER (IMC) SOFTWARE VERSION – INCONTROL TOUCH PRO 19B

NEW FEATURES INCLUDED IN THIS RELEASE:

SMARTPHONE PACK

- The Smartphone Pack* comprising of Apple CarPlay®, Android Auto™ and Baidu Carlife (China only) is now enabled for compatible vehicles

WI-FI

- Vehicle systems that were previously unable to connect to Wi-Fi for wireless software updates can now do so. This will enable future wireless InControl Touch Pro software updates for these vehicles

WIRELESS SOFTWARE UPDATES

- The wireless software update customer experience has been simplified
- New software update pending notification icon
- Along with the Wi-Fi update, wireless software updates will be available for all InControl Touch Pro vehicles

MEDIA PLAYER

- On vehicle start-up, media sources will now be remembered from the last drive cycle
- When playing a podcast, +15 seconds and -15 seconds options will be displayed

BLUETOOTH® PHONE

- Improved experience when uploading recent call list from phone to vehicle

(I-PACE ONLY)

CLIMATE CONTROL

- Climate functionality will now be fully supported when the vehicle's power is on

(ELECTRIC VEHICLES ONLY)

NAVIGATION

- Charging stations reachable with 1-4% battery charge on arrival will now be displayed
 - Charging points are more accurately displayed on route based on vehicle state of charge
-

ISSUES FIXED IN THIS RELEASE:

GENERAL/SYSTEM

- General performance improvements
- General stability improvements
- Fixed issue of no audio being available for a whole drive cycle seen in previous software version



- Side Panel theme will no longer change when the date format has been changed

AUDIO QUALITY

- General performance improvements

SMART PHONE PACK

ANDROID AUTO™

- Improved Google Maps navigation audio when playing media using Android Auto™
- When a phone is connected by Android Auto™ it will no longer also show as a Bluetooth® source
- Android Auto™ icon will now always disappear after the phone has been disconnected
- Performance improvements for audio replies to Android Auto™
- General improved stability
- The Android phone header will now be displayed with the Android Auto™ icon

APPLE CARPLAY®

- Improved display of Apple CarPlay®
- General improved stability
- When playing media from Apple CarPlay®, it will be displayed in the media view
- Performance improvements for outgoing calls made using Apple CarPlay®

BLUETOOTH® PHONE

- Fixed an issue when using the steering wheel switch to move to the next song through Bluetooth audio® source
- When system is set to French, messages will no longer be read out in English
- (Satellite Digital Audio Radio System only) Messages received when skipping through SDARS channels will no longer be lost

(CHINA ONLY)

BAIDU CARLIFE

- Improved Baidu Carlife connectivity
- General improved stability

AMBIENT LIGHTING

- Fixed an issue with the ambient lighting control screen

BLUETOOTH®

- (Chinese language only) Bluetooth® name will no longer change after switching media to Rear Seat Entertainment (RSE)
- Fixed an issue preventing Bluetooth® audio playing for a drive cycle

CD PLAYER

- Improved user experience when switching media source from Apple CarPlay® to CD

CLIMATE CONTROL

- Temperature settings and adjustments now available in the climate home screen
- Purify icon disabled when the vehicle is in defrost mode
- Third Row Climate Controls will only be available when the engine is running



- Temperature unit will no longer change from Celsius to Fahrenheit in Side Panel when language is changed to Portuguese
- Temperature control on rear screens will now work even when all zones are set to high
- (North American vehicles only) Fixed an issue of Smart Climate incorrectly showing the front passenger seat occupancy status

CONNECTIVITY

- Signal bars for vehicle connection strength will now display correctly
- When a phone is connected, Wi-Fi will now automatically enable after a power cycle
- Improved error message for data connection

RADIO

DAB RADIO

- Improved DAB reliability
- (Head Up Display (HUD) vehicles only) Media information for DAB radio will now be displayed correctly in the HUD

AM/FM RADIO

- (InControl Touch Pro Duo only) Interactive Display Module 'A' (IDMA) will now show AM not FM when AM radio is playing

SATELLITE RADIO

- Satellite Digital Audio Radio System (SDARS) will now always launch first time
- SDARS screen will now load correctly
- The correct song will now always play when selected from the satellite radio playlist
- General stability improvements

DUAL VIEW SCREENS

- Improved DVD playback image when a display theme is selected
- Display improvements for Bluetooth® settings icon

ECO DATA SCREEN

- Improved accuracy for ECO data when climate control is in ECO mode

FORWARD TRAFFIC DETECTION

- Forward Traffic Detection alert will no longer stay visible if the camera view is changed during an alert

PERSONALISATION

- Keys can now be switched to different existing user profiles

LIVE

- Live will now launch from the 'Extra Features' screen
- Fixed an issue of Live sometimes not launching
- Live will no longer skip to the first page when opening a second one
- Display improvements for Live applications

MEDIA PLAYER



- General improved stability
- Improved handling of the track duration bar
- Tracks will no longer sometimes pause 3 seconds before the end
- Correct graphic will now be shown in the background of the Instrument Panel Cluster (IPC) media panel
- Fixed an issue of resuming podcast after ending a call

NAVIGATION

STANDARD NAVIGATION

- Improved stability when resuming a route
- Improved accuracy of voice guidance
- Improved accuracy of safety cameras
- Display improvements for pop-up screens
- Improved "Send to Driver" from rear screens experience
- Improved map display during traffic side panel
- Improved map display within the Instrument Panel Cluster
- Improved reliability of address summary screen when the city selected is not unique
- Improved route calculation
- General improved reliability
- (Japan vehicles only) Rear screens will no longer display the Navigation icon
- Improved Traffic Info stability
- When the map license has been extended, the status will update immediately

ELECTRIC VEHICLE NAVIGATION FEATURES

- Navigation will no longer reset after switching the Instrument Panel Cluster to full map view
- Improved charge station searching

PARKING AID

- Fixed an issue with parking aid audio
- Fixed an issue with the parking aid 360 pop-up when in reverse

REAR SEAT ENTERTAINMENT

- Rear screens will no longer activate when opening the front console panel
- Time displayed on the rear screen will now match the front Touchscreen
- "SIRIUS XM" button is now functional in "All Settings" in Rear Seat Entertainment
- Improved performance of climate on the rear screen when using the remote control
- (Rear Massage seat vehicles only) Massage location now called 'Upper back' and 'Lower back' on the rear screens

SEAT CONTROLS

- Passenger seat icon now correctly displayed after favourite seat settings are selected
- Climate buttons will no longer be lost if the seat screen is opened multiple times in the same ignition cycle
- Improved performance of seat massage buttons

SPEECH

- Improved graphics of speech tutorial
- Improved speech 'Call contact' reliability



TELEVISION

- Television reception will now recover automatically after leaving a low reception area
- Improved performance of 'No reception' notification
- (Brazil vehicles only) Touchscreen will no longer show a blank screen after Brazil Television runs for approximately 2.5 minutes, rear screen will no longer show "No reception" message

TERRAIN RESPONSE

- Display improvements during terrain response mode
- Terrain response mode will be displayed in the correct language

TEXT TO SPEECH

- Text to speech will now behave correctly during playback

TIMED CLIMATE

- Timed climate will now use the same icon in all menus

TRANSLATIONS

- Improved translations for all languages

VALET MODE

- Improved phone reconnection when exiting valet mode

WADE SENSING

- Improved graphics for wade sensing screen when on a hill

WEB BROWSER

- A horizontal scroll bar is now displayed when a web page has been zoomed
- General speed and reliability improvements

*The Smartphone Pack is only available for vehicles equipped with either a 10" Touch Pro or 10" Touch Pro Dual View touchscreen, a SIM slot and front On-The-Go-enabled USB ports. The services offered by Apple CarPlay® depend on feature availability in your country, please see [<https://www.apple.com/ios/carplay/>] for more information. The services offered by Android Auto™ depends on feature availability in your country, please see [<https://www.android.com/auto/>] for more information.